



PROJECT SUMMARY

Bayview Environmental Services was hired as a general contractor to clear a 14-acre site for a new football field/ soccer field and new Olympic-sized pool. The project included structural demolition of the football stadium bleachers and miscellaneous buildings. Site work included asphalt and concrete removal and clear and grubbing throughout the site. Hazardous Materials remediation included abating 8 large stadium lights removing asbestos & lead at the outbuildings & removing over 5,000 LF of asbestos underground piping under a Procedure 5.

INDUSTRY

Commercial

→ Educational & Institutional

DIVISIONS

- > Environmental
- > Demolition

Site Work / Structural Demolition/ Hazardous Materials Remediation

CLIENT/OWNER

Pico Rivera Unified School District

GENERAL CONTRACTOR

Bayview Environmental Services

DURATION

4 Months

COMPLETION DATE

November 2023

CONTRACT VALUE

\$2,300,000

PROJECT SIZE

609,840 Sqft

CREW SIZE

8-10

^{*} Project Code: 23059A